



# Advanced technical service: Phi-Check




Input:




Grid coating  
on FP laminate



Forming



phi-check



To check strain distribution after forming